BLINDS 2000 PRODUCT WARRANTY

Blinds 2000 Manufacturing is committed to providing our customers with the highest standard of quality in every product we manufacture.

Blinds 2000 Manufacturing Ltd Warranty

These warranties will not apply to any Blinds 2000 Manufacturing Ltd products or parts thereof due to abuse, neglect, improper use, accident, alteration, incorrect installation, or effects due to salt air. This warranty applies to the original buyer only.

Replacement materials, hardware, or accessories will be replaced on a pro rated formula, beginning after the first year based on the time elapsed from the date of sale. Labour, service calls, and pick and delivery are not covered by this warranty.

This warranty does not cover claims from incidental or consequential damages.

All cords will eventually wear out. This is considered normal wear and tear and is not covered by this warranty.

To obtain warranty service, the purchaser must return the shades to the manufacturer.

Warranty does not cover removal, installation, or any transportation costs.

Slight variations in grain, texture, and colours are considered normal.

Removal of any Blinds 2000 Manufacturing Ltd sticker identification will void any and all warranties.

Original Bill of Sale must accompany any claim.

Verticals:

Blinds 2000 Manufacturing Ltd warranties all mechanical moving parts to be free from defect for the life of the blind. All other materials are guaranteed against stretching, twisting bowing and warping for a period of three years. All materials will gradually lose colour intensity after long exposures to the sun. Some PVC vanes may bow in the heat from direct sunlight, but will straighten when temperatures return to normal.

Aluminum Horizontal Blinds

Blinds 2000 Manufacturing Ltd warranties all mechanical moving parts to be free from defect for the life of the blind. Slats are guaranteed against peeling for a period of three

years. Ultrasonic cleaning can cause peeling. Warranty is void if manufacturer's specifications are exceeded (e.g. oversized).

Euro, Faux, Alternative Woods:

Blinds 2000 Manufacturing Ltd warranties all mechanical moving parts to be free from defect for the life of the blind. Slats are guaranteed against excessive warping for a period of three years. All materials will gradually lose colour intensity after long exposures to the sun. Warranty is void if manufacturer's specifications are exceeded (e.g. oversized).

B2k Wood Venetian:

Blinds 2000 Manufacturing Ltd warranties all mechanical moving parts to be free from defect for the life of the blind. Slats are guaranteed against chipping, peeling, and excessive warping for a period of three years. Wood is a natural product and therefore nominal warping may occur especially with fluctuations in humidity. All materials will gradually lose colour intensity after long exposures to the sun. Slight variations in grain, texture and colour are considered normal. Warranty is void if manufacturer's specifications are exceeded (e.g. oversized).

Vienna Shades:

Blinds 2000 Manufacturing Ltd warranties all mechanical moving parts to be free from defect for the life of the blind. Knitted fabrics may experience minor weave variations due to heat, humidity, and other room conditions. These variations can result is light bowing, puckering, and dimpling of the fabric. This is considered normal and does not constitute a failure in either workmanship or materials. The possible variations are minor and have been shown in case studies, not to detract from the beauty of the product.

Pleated and Cellular Shades:

Blinds 2000 Manufacturing Ltd warranties all mechanical moving parts to be free from defect for the life of the blind. Fabrics are warranted for a period of three years. All materials will gradually lose colour intensity after long exposures to the sun.

Roller and Roman Shades:

Blinds 2000 Manufacturing Ltd warranties all mechanical moving parts to be free from defect for the life of the blind. Fabric is warranted for a period of three years. Shades may experience minor weave variations due to heat, humidity, and other room conditions. These variations can result is light bowing, puckering, and dimpling of the fabric (along the bottom rail). This is considered normal and does not constitute a failure in either workmanship or materials. All materials will gradually lose colour intensity after long exposures to the sun.